SOUTH DAKOTA WATER W	ELL COMPLETION REPORT	07-92
LocationNW¼SW¼ Sec12Twp116Rg72	Well Owner: Burton & Perry Baloun	
	Business Name: HC #1	
County	Address: Box 68A	
Hyde	Highmore, SD 57345	
Please mark well location with an "X"		
X X	WELL LOG:	DEPTH
W	FORMATION	FROM TO
	Top Soil	0 2
-+- -+-		
	Gravel	2 30
	Gravel	30 45
1 Mile ————	Shale	45 1090
Well Completion DateJuly 22, 1994	Greenhorn	1090 1120
The completion but a second control of the control		
	Shale	1120 1560
LOCATION:	Dakota Sand	1560 1720
Distance from nearest potential pollution source (septic tank, abandoned well,	Morrison	1720 1855
feed lot, etc.)? 7500 ft. from Septic Tank (identify source).	Sundance	1855 2040
PROPOSED USE:		
Municipal ☐ Business ☐ Test Holes		
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well		
METHOD OF DRILLING:		
Rotary		
1100027		
	1900	
CASING DATA:		<u> </u>
Steel 🖾 Plastic 🖾 Other	STATIC WATER LEVEL	Feet
If other describe <u>Copper</u>	If flowing: closed in pressure150	PSI
PIPEWEIGHT DIAMETER FROM TO HOLE DIAMETER	GPM flow 100 through 2	inch pipe
#250 LB/FT 5 IN 0 FT 300 FT 7 7/8 IN	Controlled by 🖾 Valve 🗆 Reducers 🗆 Other	r
#80 LB/FT 2 IN 0 FT 1840 FT 4 1/2 IN	Reduced Flowrate15	GPM
#K LB/FT 2 IN 1840 FT 2040 FT 4 1/2 IN	Can well be completely shut in? <u>Yes</u>	
GROUTING DATA		
Grout Type No. of Sacks Grout Weight From To 15 No. of Sacks Brout Weight From To 16	WELL TEST DATA:	
IU./ yaiILIL		****
lb./galftft	Bailed	
Describe grouting procedure Pressure Plug	Other	
	Pumping Level Below Land Surface	
	ft. AfterHrs. pumped _	GPN
	ft. AfterHrs. pumped _	GPN
SCREEN: Perforated pipe Manufactured	If pump installed, pump rate	GPM
Diameter 2" IN Length 200' FEET		
MaterialCopper	REMARKS	31-1294
Slot Size 3/8" Set From 1840 Feet to 2040 Feet	[~ (3) (3)
Other information		ATE IS S
Const information	88.8	10 C8 = 1
	[\frac{1}{2}\cdot \frac{1}{2}\cdot \frac	The Principal
	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	1. W. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
		1505018177
WAS A PACKER OR SEAL USED? ☑ YES ☐ NO		
If so, what material? Rubber	This well was drilled under license # 94	-
Describe packer(s) and location? Above Perforations	And this report is true and accurate.	
DISINFECTION:	Drilling firm Huron Drilling Inc.	
Was well disinfected upon completion?YES, How:	Signature of License Representative:	
x_NO, Why Not? Flowing Well		
	1— <u>1</u>	
	Signature of Well Dwne or Equitable Property Holder	r:
	1 /4/	
Laboratory sent to for water quality analysis Pierre, SD 57501	Date:July 26, 1994	1011010
	•	19/19/94